SWIMMING POOL OFFICIAL INSPECTION REPORT

GLENN COUNTY ENVIRONMENTAL HEALTH

225 N. Tehama Street, Willows, CA 95988 Phone (530) 934-6102 FAX (530) 934-6103

Page 1 of

Name of Facility / DBA: Name of Facility / DBA: Name of Facility / DBA:								Inspection Date:		
Address:								Reinspection Date (one or after):		
Owner/Permittee:						per		(Reinspections are subject to fees) Inspection Time: Permit Expiration Date:		
Pool Type: ☐ Swimming Pool ☐ Spa Pool ☐ Wading Pool ☐ Interactive Water Feature ☐ Other						Service: Routine Inspection Reinspection Complaint Construction/Pre-Opening Other				
PH: Free Chlorine: Combined					id: Flow Rate:		_	Temperature: Other:		
	Regulations: California He			et. seq.; Cali	fornia Code o			hapter 31 & Title 22, (Chapter 20	
Pool Construction Water Qualit					G			eneral Facilities		
 Pool Shell Bottom & Sides Decks & Coping Diving Boards Depth Markers Ladders/Steps/Railings Underwater Lighting & Electrical 			18.	nlorine/Bro vanuric Act ebris in Poo ater Clarity mperature	omine d ol		32. [33. [34. [35. [36. [E MAN AL MAN ANNO MAN CO		
Recirculation Equipment 8. ☐ Filters 9. ☐ Pumps 10. ☐ Flowmeter 11. ☐ Pressure/Vacuum Gauges 12. ☐ Skimmers & Gutters 13. ☐ Pipes & Fittings 14. ☐ Chemical Feeders 15. ☐ Water Supply/Backflow Prevention			Safety Equipment 23. Gates/Enclosure 24. Drain Covers 25. Anti-Entrapment St 26. Rescue Pole 27. Life Ring 28. Safety Signs 29. First Aid Kit 30. Chlorine Gas Safety			ff	38.	cellaneous Chemical Test Kits Chemical Testing Frequency Record Keeping Lifeguards Communicable Disease Control Site Supervision & Control General Sanitation Other:		
Comments:										
1) The pool Shell is abserved to be garacking, forming small divets. The smooth surface is deterturating. Replaster pool to prevent injury to all person.										
				1000	-					
N 18018 12					-					
		35.00								
						2				
							200000			
		gardan a		*				***		
								1 1 1		
Received By:	Wartin	(05	tillar	1050	REHS	S:	121	letto		