

SWIMMING POOL OFFICIAL INSPECTION REPORT

GLENN COUNTY ENVIRONMENTAL HEALTH

247 North Villa Avenue, Willows, CA 95988

Phone: (530) 934-6102 • Fax: (530) 934-6103

Page 1 of 1

Name of Facility/DBA: VILLA COURT TOWNHOMES		Inspection Date: 7/2/18	
Address: 127 VILLA COURT, WILLOWS, CA 95988		Reinspection Date (on or after): N/A <small>(Reinspections are subject to fees)</small>	
Owner/Permittee: VILLA COURT TOWNHOMES / INVESTORS	Phone Number:	Inspection Time: 3:30-4	Permit Expiration Date:
Pool Type: <input checked="" type="checkbox"/> Swimming Pool <input type="checkbox"/> Spa Pool <input type="checkbox"/> Wading Pool <input type="checkbox"/> Interactive Water Feature <input type="checkbox"/> Other		Service: <input type="checkbox"/> Routine Inspection <input type="checkbox"/> Reinspection <input type="checkbox"/> Complaint <input checked="" type="checkbox"/> Construction/Pre-Opening <input type="checkbox"/> Other	
pH:	Free Chlorine:	Combined Chlorine:	Cyanuric Acid:
Flow Rate:	Temperature:	Other:	
* CHEMICALS NOT TESTED DURING CONSTRUCTION INSPECTION			
<small>Applicable Laws & Regulations: California Health & Safety Code § 116025 et. seq.; California Code of Regulations Title 24, Chapter 31 & Title 22, Chapter 20</small>			

Pool Construction 1. <input type="checkbox"/> Pool Shell 2. <input type="checkbox"/> Bottom & Sides 3. <input checked="" type="checkbox"/> Decks & Coping 4. <input type="checkbox"/> Diving Boards 5. <input type="checkbox"/> Depth Markers 6. <input checked="" type="checkbox"/> Ladders/Steps/Railings 7. <input type="checkbox"/> Underwater Lighting & Electrical	Water Quality 16. <input type="checkbox"/> pH 17. <input type="checkbox"/> Chlorine/Bromine 18. <input type="checkbox"/> Cyanuric Acid 19. <input type="checkbox"/> Debris in Pool 20. <input type="checkbox"/> Water Clarity 21. <input type="checkbox"/> Temperature 22. <input type="checkbox"/> Flow Rate/Turnover	General Facilities 31. <input type="checkbox"/> Exterior Lighting 32. <input type="checkbox"/> Indoor Ventilation 33. <input type="checkbox"/> Restrooms & Toilets 34. <input type="checkbox"/> Handwash Sinks 35. <input type="checkbox"/> Dressing Rooms 36. <input type="checkbox"/> Showers 37. <input type="checkbox"/> Drinking Fountains
Recirculation Equipment 8. <input type="checkbox"/> Filters 9. <input type="checkbox"/> Pumps 10. <input type="checkbox"/> Flowmeter 11. <input type="checkbox"/> Pressure/Vacuum Gauges 12. <input type="checkbox"/> Skimmers & Gutters 13. <input type="checkbox"/> Pipes & Fittings 14. <input type="checkbox"/> Chemical Feeders 15. <input type="checkbox"/> Water Supply/Backflow Prevention	Safety Equipment 23. <input type="checkbox"/> Gates/Enclosure 24. <input type="checkbox"/> Drain Covers 25. <input type="checkbox"/> Anti-Entrapment Shutoff 26. <input type="checkbox"/> Rescue Pole 27. <input type="checkbox"/> Life Ring 28. <input type="checkbox"/> Safety Signs 29. <input type="checkbox"/> First Aid Kit 30. <input type="checkbox"/> Chlorine Gas Safety	Miscellaneous 38. <input type="checkbox"/> Chemical Test Kits 39. <input type="checkbox"/> Chemical Testing Frequency 40. <input type="checkbox"/> Record Keeping 41. <input type="checkbox"/> Lifeguards 42. <input type="checkbox"/> Communicable Disease Control 43. <input type="checkbox"/> Site Supervision & Control 44. <input type="checkbox"/> General Sanitation 45. <input type="checkbox"/> Other:

Comments:

**** CONSTRUCTION INSPECTION ON POOL REMODEL ****

- POOL SHALL REMAIN CLOSED UNTIL CONSTRUCTION DEFICIENCIES ARE CORRECTED. (SEE BELOW).

③ POOL DECKING, ALONG THE WEST SIDE NEED TO BE PROPERLY SLOPED SO THAT ^{SURFACE} WATER RUNS AWAY FROM POOL.

③ DECK TEXTURE IS TOO ROUGH AND NEEDS TO BE SURFACED SO THAT IT IS NOT SO ROUGH.

③ CANTILEVERED DECK WAS DONE INCORRECTLY. CANTILEVER MUST EXTEND AT LEAST 1" OVER COPING AND NOT MORE THAN 2". (SEE PLANS)

⑥ POOL LADDER SPACING CAN BE NO GREATER THAN 5" AWAY FROM THE POOL WALL AND NOT LESS THAN 3".

Received By: Kathleen Miller REHS: Andrew Perry